



Source : <https://www.sortirdunucleaire.org/Etats-Unis-Nine-Mile-Point-incendie-de-plus-de-15>

Réseau Sortir du nucléaire > Informez

vous > Des accidents nucléaires partout > **Etats-Unis : Nine Mile Point : incendie de plus de 15 minutes dans le bâtiment turbine du réacteur n°2**

1er février 2018

Etats-Unis : Nine Mile Point : incendie de plus de 15 minutes dans le bâtiment turbine du réacteur n°2

L'incendie, qualifié de "petit", s'est déclaré suite à la tentative de réparation d'une fuite de vapeur au moment où l'équipement d'injection a fui sur une tuyauterie chaude. Il n'y aurait eu aucun dommage et le feu a été éteint par les pompiers sans assistance extérieure au site. L'incendie est dû à l'utilisation de Furmanite pour réparer une soupape de contrôle de débit d'entrée du réchauffeur du séparateur d'humidité. A noter que les réparations s'effectuent à la volée, sur du matériel qui participe au fonctionnement d'un réacteur à 100 % de sa puissance !



Type : BWR Mark 2 - Puissance : 3 988 MWth - Première divergence : 05 / 1987 -

Available in english only

Event Number : 53190

Facility : NINE MILE POINT - State : NY

Unit : [2] - RX Type : [2] GE-5

Event Date : 02/01/2018 - Event Time : 11:08 [EST]

Emergency Class : UNUSUAL EVENT 10 CFR Section : 50.72(a) (1) (i) - EMERGENCY DECLARED Person (Organization) :

Initial PWR : 100 % Current PWR : 100 %

Event Text

UNUSUAL EVENT - FIRE IN THE TURBINE BUILDING LASTING GREATER THAN 15 MINUTES

"Nine Mile Point unit 2 experienced an unusual event due to a small fire in the turbine building that was immediately extinguished and then reflash. The fire was declared out at 1119 [EST], 2/1/18. The fire was caused when steam leak repair injection equipment failed and leaked onto hot piping. There was no equipment damage or impact to plant operation. The fire was extinguished by the fire brigade. Offsite assistance was not required."

The fire resulted from Furmanite repair of a Moisture Separator Reheater inlet flow control valve. The unusual event will be terminated when sufficient lagging is removed to verify the extent of leaked fluid.

The licensee notified the NRC Resident Inspector.

Notified DHS SWO, FEMA, DHS NICC, and NNSA (via e-mail).

* * * UPDATE AT 1240 EST ON 2/1/2018 FROM ANTHONY PETRELLI TO MARK ABRAMOVITZ * * *

The unusual event was terminated at 1211 EST.

The licensee notified the NRC Resident Inspector.

Notified the R1DO (Janda), NRR EO (Miller), IRD MOC (Grant), DHS SWO, FEMA, DHS NICC, and NNSA (via e-mail).

<https://www.nrc.gov/reading-rm/doc-collections/event-status/event/2018/20180202en.html>