Réseau
Sortir du nucléaire

Réseau "Sortir du nucléaire"
9 rue Dumenge - 69317 Lyon
Tél : 04 78 28 29 22 Fax : 04 72 07 70 04
www.sortirdunucleaire.org

Fédération de plus de 930 associations et 60 000 personnes, agrée pour la protection de l'environnement

Source : https://www.sortirdunucleaire.org/Etats-Unis-QUAD-CITIES-ALERTE-declaree-suite-a-un

1er février 2017

Etats-Unis : QUAD CITIES : ALERTE déclarée suite à un incendie survenu sur un matériel associé à la sûreté

Un incendie est survenu sur le panneau de la salle de commande principale de l'unité 2. L'arrêt d'urgence n'aurait pas été nécessaire. L'incendie a été éteint 3 minutes plus tard et le réacteur est resté à 100% de puissance.

L'alerte a été déclarée à 19 h 38 soit 9 minutes après le départ de l'incendie.

L'initiateur de l'incendie serait un changement d'ampoule mais l'origine du problème est en cours d'étude.

L'électricien a fait une déclaration suite aux dégâts occasionnés à un interrupteur.

*** * * MISE À JOUR À 00 h 40 EST LE 2/2/17**

L'alerte a été levée 3 h 58 après son déclenchement. L'électricien a déclaré que l'incendie était éteint et qu'aucun autre matériel n'avait été affecté par l'incendie.

Type Fukushima I (BWR Mark I) - Puissance 2 597 MWth - Première divergence : 04/1972

available in english only

Event Number : 52527

Facility : QUAD CITIES

State : IL - Unit : [2] RX

Type : [1] GE-3,[2] GE-3

Event Date : 02/01/2017

Event Time : 19:38 [CST]

Last Update Date : 02/02/2017 **Emergency Class : ALERT** 10 CFR Section : 50.72(a) (1) (i) -

EMERGENCY DECLARED

Initial PWR : 100 % Current PWR : 100 %

Event Text

ALERT - FIRE IN SAFETY RELATED SYSTEM

"On February 1, 2017, at 1929 hours [CST], a fire was discovered on the Unit 2 Main Control Room panel 902-3 in the 3E ERV/ADS valve switch. A reactor SCRAM was not required. No automatic isolations/actuations occurred. The fire was extinguished at 1932 and the reactor remained at 100% power.

"An Alert was declared at 1938 [CST].

"The initiation of the event was attempting to change a light bulb. The cause of the event is under investigation.

"The Senior Resident Inspector has been notified of the event."

The licensee entered a 14 day Technical Specification Action statement as a result of the damage to the switch.

Notified DHS SWO, DOE, FEMA, HHS, NICC, USDA, EPA, FDA, NNSA (e-mail), and NRCC SASC (e-mail).

* * * UPDATE AT 0040 EST ON 2/2/17 FROM DAVID KNEPPER TO JEFF HERRERA * * *

Notified that the Alert was terminated at 2336 CST on 2/1/17. The licensee stated that the fire was extinguished and an extent of condition walkdown did not identify any additional equipment damage as a result of the fire. The licensee will be issuing a press release.

The licensee will be notifying the NRC Resident Inspector.

https://www.nrc.gov/reading-rm/doc-collections/event-status/event/2017/20170203en.html