

Source : <https://www.sortirdunucleaire.org/Etats-Unis-BRUNSWICK-notification-du-deces-d-un>

Réseau Sortir du nucléaire > Informez

vous > Des accidents nucléaires partout > **Etats-Unis : BRUNSWICK : notification du décès d'un sous traitant**

11 juillet 2016

Etats-Unis : BRUNSWICK : notification du décès d'un sous traitant

Vers 16 h 14, La salle de commande principale a été informée qu'un employé sous-traitant avait un problème de santé. Les premiers intervenants se sont rendus sur les lieux en quelques minutes. L'assistance extérieure a été sollicité et est arrivé sur place vers 16 h 41. Les personnels hospitaliers ont noté, vers 17 h 45, que le patient était décédé à 17 h 10. Cette personne était en dehors de la zone contrôlée et sans implication de matériel radioactif. La cause du décès n'a pas encore été déterminée.

Type : Fukushima 1 (BWR Mark 1) - Puissance 2 923 MWth - Première divergence : n° 1 : 10 1976 - n°2 : 03 / 1975

Available in english only

Event Number : 52080

Facility : BRUNSWICK - State : NC

Unit : [1] [2] - RX Type : [1] GE-4,[2] GE-4

Event Date : 07/11/2016 Event Time : 17:45

Emergency Class : NON EMERGENCY 10 CFR Section : 50.72(b)(2)(xi) - OFFSITE NOTIFICATION

Initial PWR Initial RX Mode Current PWR 1 N Y 100 Power Operation 100 Power Operation 2 N Y 100 Power Operation 100 Power Operation

Event Text OFFSITE NOTIFICATION DUE TO NON-WORK RELATED ON-SITE CONTRACTOR FATALITY

"At approximately 1614 Eastern Daylight Time (EDT), the Main Control Room was notified of a contracted employee experiencing a non-work related medical issue near the Discharge Weir. First Responders were immediately dispatched and present at the scene in minutes. Off-site assistance was requested and arrived on-site at approximately 1641. Doshier Memorial Hospital officials notified

the plant at approximately 1745 that the patient was declared deceased at 1710. The individual was outside of the protected area (within the owner controlled area), and no radioactive material or contamination was involved. The cause of death has not yet been determined.

"This notification is being made in accordance with 10 CFR 50.72(b)(2)(xi) for situation related to the health of on-site personnel for which a notification to other government agencies is planned. The Occupational Safety and Health Administration (OSHA) will be notified.

"The NRC Resident Inspector has been notified.

"This event did not result in any adverse impact to the health and safety of the public."

The licensee completed their notification to OSHA at 1835 hours.

<https://www.nrc.gov/reading-rm/doc-collections/event-status/event/2016/20160712en.html#en52080>