

Source : <https://www.sortirdunucleaire.org/Une-nouvelle-centrale-nucleaire-2295>

Réseau Sortir du nucléaire > Informez

vous > Nos dossiers et analyses > ancien blog : Alerte nucléaire au Japon > **Une nouvelle centrale nucléaire est hors contrôle**

12 mars 2011

Une nouvelle centrale nucléaire est hors contrôle

00h00 - La radioactivité s'étend en dehors de la centrale de Fukushima Daiichi (1). La centrale de Fukushima Daini, à 11 kilomètres de la centrale de Fukushima Daiichi, connaît à son tour de graves problèmes.

Tepco, l'exploitant des deux centrales voisines a annoncé que la température des réacteurs 1 et 2 de la centrale de Fukushima Daini augmentait et qu'il avait perdu le contrôle sur la pression dans les réacteurs (2).

(1) "Japan's Nuclear and Industrial Safety Agency said early Saturday that some radiation — it was not clear how much — has also seeped outside the plant, prompting widening of an evacuation area to a six-mile radius from a two-mile radius around the plant."

https://today.msnbc.msn.com/id/42025882/ns/world_news-asiapacific/

(2) "Tokyo Electric Power Co. said Saturday that the temperatures of its No.1 and No.2 reactors at its Fukushima Daini nuclear power station were rising, and it had lost control over pressure in the reactors." https://today.msnbc.msn.com/id/42025882/ns/world_news-asiapacific/