Réseau
Sortir du nucléaire

Réseau "Sortir du nucléaire"
9 rue Dumenge - 69317 Lyon
Tél : 04 78 28 29 22 Fax : 04 72 07 70 04
www.sortirdunucleaire.org

Fédération de plus de 930 associations et 60 000 personnes, agrée pour la protection de l'environnement

Source : https://www.sortirdunucleaire.org/Explosion-a-la-centrale-de

12 mars 2011

Explosion à la centrale de fukushima

Une explosion a eu lieu dans le réacteur n°1 de la centrale de Fukushima Daiichi (1). La structure externe du bâtiment réacteur aurait explosée (2). "L'explosion s'est produite entre 15H30 et 16H00 dans le réacteur N°1 de la centrale nucléaire, située à 250 km au nord de Tokyo" (3)

Photo du réacteur après l'explosion

(1) "Jiji news agency said there had been an explosion at the stricken 40-year-old Daichi 1 reactor and TV footage showed vapor rising from the plant"
https://www.reuters.com/article/2011/03/12/us-japan-quake-idUSTRE72A0SS20110312

(2) "NHK television said the outer structure of the building that houses the reactor appeared to have blown off, which could suggest the containment building had already been breached."

(3) AFP 12.03.11 9h58 Japon : explosion à la centrale nucléaire de Fukushima